

Prepared By
Birendra Kishan
(Lect. Mechanical Engg).

→ Cutting Tool:-

mechanical instrument used to remove material from the workpiece.

Types of tool

Single cutting tool

- 1) Single point cutting tool → Lathe, shaping, honing, grinding etc.
→ MRR is less
- 2) Multi point cutting tool
→ more than one cutting tip
→ milling, grinding, broaching etc.

Properties of cutting tool

- At least 30 to 50% harder than w.p.
- High hot hardness temp
- High toughness
- High wear resistance
- Higher thermal conductivity
- Easy to fabricate and cheap.
- High strength
- Low coefficient of friction (Good surface finish)

1) High carbon steel

C = 0.8 to 1.3%

→ Hot hardness temp = 250°C

Si = 0.1 to 0.4%

Mn = 0.1 to 0.4%

→ Very high toughness.
→ strength upto RC-65

→ method of production = forging

→ Re-grindable

→ cutting velocity

→ Used for milling of soft metal → 5 m/min

→ Chisel are made by (Al, Ag, copper, brass, ~~steel~~ etc) due to higher toughness

2) High speed steel

General used HSS is

18-4-1 → Vanadium

↓ ↓ ↓
Tungsten Chromium (maintaining
(for (to increase to wear
increase strength) resistance)
in hot hardness & Rest iron.
Temp)

Rest iron

→ Sometimes molybdenum is used in place of Tungsten, ~~but~~ low price but wear resistance in low.
→ shouldn't ~~be~~ used in

① Hot hardness temp. 600°C

→ High toughness

→ manufacturing method - forging

→ Recommendable

→ shouldn't be used in cutting in High Carbon Steel due to iron containing HSS in the steel diffused to the body of the steel

→ Uses

→ cutting tool of lathe (turning, ~~plow~~ drill heads, milling cutter)

→ shouldn't be used for high carbon steel.

→ cutting velocity - 40 to 50 m/min

② Stellite → non ferrous cast alloys

→ Cobalt - 40 to 50%

Chromium - 27 to 35%

Tungsten - 15 to 22%

Carbon - 2 to 4%

→ manufactured by casting method

→ total body is made up by same metal

→ hot hardness

temp 800°C

→ same as HSS

→ Replacement of HSS only increase in cutting velocity

Carbides

④ Non-ferrous cast Alloys (carbides)

④ Cemented carbides

③ speed up to 6 to 8 times of HSS.

② → Produced by powder metallurgy technique with ~~sintering~~ at 1000°C .

→ They are very stiff and young modulus is about 3 times of the steel.

① → 2 types of carbides

a) Tungsten carbides

b) cemented or cemented carbide

③ can't be regrindable, means ~~throw out~~ throw away type of tool.

→ Hot hardness temp = 1000°C

→ Toughness is less than HSS.

→ max cutting velocity 300 m/min - 350 m/min

→ High wear resistance

→ low coefficient of thermal expansion

→ High thermal conductivity,

Used : Types

- (P₁₀, P₂₀, P₃₀, P₄₀, P₅₀)
- a) P-type - machining of ferrous materials & steel.
- b) K-type - machining of non-ferrous non-metals & cast iron.
- (K₁₀-K₅₀)
- c) M-type - Gentle purpose of cutting of (M₁₀-M₅₀) cast iron.

5) Ceramics

- It is
- Basically Al₂O₃
- made by powder metallurgy
- use for very high speed 500 m/sec.
- can withstand upto 1200°C.
- very high Abrasion resistance
- used for machining CI and plastics
- Throw away type of tool means not negotiable.
- highly brittle & low toughness.
- can't be used for intermittent operation & only for continuous use.

6) Cermets (~~ceram~~)

- composition ceramic - 90%
Combination of ~~ceramic~~ ceramic and metal
- produced by powder metallurgy
- 90% ceramic + 10% metal.
- To reduce brittleness & increase toughness
small amount of metal bond
- powder metallurgy method used for manufacturing
- $V_{max} = 400 - 500 \text{ m/min}$
- Intermittent feed also (replacement of ceramic).

7) Diamond

- It has extreme hardness
- Low thermal expansion
- High thermal conductivity
- Low coefficient of friction
- $V_c \text{ max} = 1500 \text{ to } 2000 \text{ m/min}$
- not used for milling of ~~carbon~~ ferrous metals
due to diffusion of carbon atom
→ withstand upto 1500°C .

- made by powder metallurgy
- used for turning, boring of tools, milling cutters, grinding wheels, honing tools, grinding wheel.

87 CBN - cubic boron nitride

consist of

→ composition: - Atoms of nitrogen and boron produced by powder metallurgy

→ used as substitute for diamond during milling of steel.

→ used as grinding wheel on HSS tools

→ Excellent surface finish obtained.

87 UCON

→ Developed by Union Carbide in USA

→ consist of columbium 50%, Titanium 30%, tungsten 20%.

→ made by

107 Stalon (Si-Al-O-N)

- made by powder metallurgy with milled powder of silicon, Nitrogen, Aluminium and oxygen
- more toughness than ceramics, so it can be used by intermittent cut
 - Cutting speed - 2 to 3 times to Ceramics
- used in many of Aerospace Alloys
Nickel based gas turbine blade with a cutting speed of 30, 5 m/sec.

Elements properties

- Tungsten - Increase hot hardness
Hard carbides formed, Improving
abrasion Resistance



molybdenum - Increasing hot hardness
Hard carbides formed, Improving
Abrasion Resistance.


Chromium :- Depth hardenability of using heat treat hard carbides, formed, Improving abrasion resistance some corrosion Resistance

~~Vanadium~~
Vanadium combines with carbon for wear resistance retards grain growth for better toughness.





Cobalt :- Increase hot hardness, toughness
Carbon :- Hardening element forms carbides

→ ~~of~~ movement of tool over the surface of work of WIP per unit time.





Top view



flute :- Through which chip flows.

Cutting edges :- Edges that carries out cutting

nose :- Corners, are on chamfer at Junction of major and minor cutting edge

- flank :- Surface ^{which faces} ~~below~~ cutting edge work piece.

Tool angles

Angle that influence tool performance to a considerable extent and therefore proper selection is necessary

shank :- main body of the tool.

Rake face

- Allows flow of chip convenient direction.
- Gives sharpness to cutting edge.
- Increase tool life.
- Reducing cutting forces required to shear

Back rake angle

It is

~~measured~~

→ Angle made by the rake face of the tool with respect to the horizontal plane measured in the length direction.

→ It allows the chip to flow in convenient direction.

→ It reduce the cutting force required to shear the metal. ~~and increase~~ therefore it increases the tool life.

the rake angle used when

- mix of work hardening component
- mix of low strength ferrous and non-ferrous material.
- Turning long shaft of small diameter

→ -ve rake angle used when

- used with tool material which are very weak in tension like carbide tools.
- mix of high strength alloy
- Interrupted cuts and heavy feed rates are to be used.

→ ~~mixing~~

side rake angle

→ Angle made by the rake face with respect to the horizontal plane measured in the width direction.

→ It guides the direction of the chip away from the w/p.

End cutting edge angle

→ Angle betw face of the tool and plane perpendicular to the side of the shank. flank.

→ It acts as a relief angle that it allows small sections of the end cutting edge to contact the turning machine surface to ~~avoid~~ and prevent chatter and vibration.

Side cutting edge angle

→ It is angle betw the side cutting edge and the longitudinal axis of the tool.

→ It avoids the formation of BUE, control the direction of chip and distributes the cutting force

• Advantage of increase in cutting edge angle

→ Increases tool life, for same depth of cut the cutting force distributed on a wider surface.

→ It diminishes the chip thickness for the same amount of feed and permits greater cutting speed.

→ Large cutting edge angles are likely to cause the tool to chatter

Side relief angle

→ Angle made by the flank of the tool and plane perpendicular to the base ~~under~~ under the side cutting edge.

→ This angle permits the tool to be fed side way into the job so that it can cut rubbing

End relief angle

→ It is the angle made by the end flank and plane perpendicular to the base. This angle prevents the cutting tool from rubbing against the job.

Now Radius

- It is preferred to increase the surface finish and strength of cutting tip of the tool.
- Small radius produces smooth surface finish and are used on thin cross section of work.
- Large radius strengthens the tool and are used on cast iron and casting.
- TOO large radius induces chatter.


Rake - side face
 Cutting - side end
 Relief - side and neck

Relief Angle

→ ~~Cutting using angle~~

Basically there are 2 types of system to designate tool geometry of single point cutting tool




Cutting using single point cutting tool can be affected by rake angle of tool and the nose radius of the tool. The arrangement of all these in a particular order is called as single point cutting tool.



1) ASA - Angle are ~~made defined~~ measured w.r.t to perpendicular plane

2) ORS - Angles are measured w.r.t to plane containing principal side cutting edge and the plane normal to it.

3) Enclination angle - $i - \alpha' - \alpha' - \alpha' - \alpha' - r$ (approach/principal cutting edge angle)



Effect of Tool Geometry on machining

Back rake angle

- ~~It is the angle betw the face of the tool and a~~
- With increase in back rake angle the chip is getting curly and moving away from somewhere in the middle of the rake face. Hence the length of contact betw chip and rake face will be shorter, frictional energy losses are reducing and there fore force and power consumption reducing.
- Even though strength of tool is reduced with the increase in rake angle, if at all tool is failing because of strength, it is considered as abnormal failure of the tool ~~only~~.
- But the increase in rake angle when the forces and machining are reducing the tool wear reducing and therefore same tool can be used for longer duration.

~~and therefore~~

hence the tool life is increased.

→ The contact area between tool tip and work piece is called as wear land.

→ With increase in back rake angle tool the length of the tool, wear out for inducing the required amount of time, will be longer therefore the time taken for longer length of the tool to be worn out is longer. Hence the tool life is increased.

→ max back rake angle used is only 45° because beyond 45° increase in back rake angle will cause the drastic reduction in the strength of the tool.

→ Zero back angle used when machining of brass work piece. and also on thread cutting operation.

→ Generally back rake angle not affecting the surface finish produced on the work piece but during machining of brass w/p by keeping all other parameters remains constant with changing in back rake angle it is found that surface finish changing and it is found that at zero rake angle it is producing better surface finish.

② Side rake angle

$\alpha_s \uparrow$
Strengths \downarrow
force \downarrow
power \downarrow
Tool \uparrow

→ with increase in side rake angle amount of chip bending in width direction reducing.

$$\alpha_s = 5 \text{ to } 45^\circ$$

③ Relief angle

→ with zero relief angle of the tool cannot penetrate into the work piece and the tool is on the work piece without



Simply rubbing
doing any machining

$$\alpha_r = 5 \text{ to } 15^\circ$$

$$\alpha_s = 5 \text{ to } 15^\circ$$

④ Cutting edge (α_e, α_s)

→ If the end cutting angle increases nose radius decreases, therefore surface finish produced with the

→ with increase in

on the machined surface is ~~reduced~~ reduced.

→ with increase in side cutting edge angle, the nose radius increased therefore the surface finish produced on the machined surface is reduced.

$$\alpha_e = 8 \text{ to } 20^\circ$$

$$\alpha_s = 0 \text{ to } 90^\circ \text{ (} 65^\circ \text{ to } 90^\circ \text{ preferable)}$$

⑤ Nose Radius

- As the nose radius increasing the surface finish produced on the machined surface ~~noted~~ producing is better but on the other hand with increase in nose radius the surface contact betw tool and w/p increases therefore the vibration induced during machining will be increasing.
- Due to increase in vibration, the chattering start, and chattering mark is produced which damages the surface finish.
- The optimum nose radius which gives better surface finish 0.2 to 1.2 mm.

Cutting Speed

- cutting speed of cutting tool can be defined as the rate at which its cutting edge passes over surface of the w/p in unit time.
- It is normally expressed in terms of surface speed in meters per minute.
- If it is too high the tool will be ~~not~~ get over heated and its cutting edge may fail.
- If it is too low, the time consumed in machining and full cutting capacities of the tool and machine are not utilized which results in lowering of productivity and increases the production cost.

feed

→ It is defined as the distance travelled along or into the work piece for each pass of c/c point through a particular ~~cut~~ position.

→ for single point

→ ~~Eg of In lathe~~

Eg: In turning operation on a lathe it is equal to the advancement of tool correspondingly to each revolution of work. (mm/rev)

(H) In milling, the feed is basically considered per tooth of the cutter which is (feed/rev)

(III) In planing, it is the work feed and not the tool.

Depth of Cut -

→ It is the penetration of the cutting edge of the tool into the w/p material in each pass, measured ~~per~~ perpendicular to the machined surface.

→ It determines the thickness of metal layer removed by the cutting tool in one pass.

cutting fluid

Cutting fluid sometimes referred to lubricants or coolants are liquid and gases applied to the tool and w/p to assist the cutting operation.

Purpose of cutting fluid

(1) TO COOL THE TOOL

cooling is necessary to prevent metallurgical damage and to assist in decreasing friction at the tool chip interface

(ii) TO cool the work piece

107

(iii) TO lubricate and reduce friction

(iv) TO improve surface finish

(v) TO cause chips breaks up into smaller parts

(vi) TO wash the chip away from the tool

(vii) ~~It~~ prevents corrosion of chips and machine properties of cutting fluid

→ Highly heat absorption capacity

→ It should possess good lubricating properties

→ It should be non-corrosive to work piece and machine

→ Low viscosity to permit free flow of the liquid.

→ It should be non-toxic to operating person

→ It should be stable in use and storage

→ It should be safe

→ It should permit clear view of work

→ low priced to minimize the cost of production

most commonly used cutting fluids are

(i) cast iron:- no cutting fluid is used

(ii) steel - kerosene oil + mineral oil


(iii) Alloy steel:- sulphur based oil + mineral oil

(iv) copper:- soluble oil with 90% to 95% of water

(v) Aluminium - mineral with soluble oil.


Hack-saw blade

- A Hack-saw blade is a multi-point cutting tool has a very large number of wedge like points each with its own rake and clearance angle. is used to cut steel and other metals.
- The rake is necessary but too much rake makes the teeth weak.
- It is also necessary to have clearance angle. If there ^{is} no clearance angle then a large amount of ~~frictional force~~ ^{energy} will be lost to overcoming the frictional force.
- High speed steel blades are used for cutting of tough, resistant material while high Carbon steel are used for general cutting.




Chisel

- A chisel is a single point cutting tool ~~used to~~ with a wedge shaped cutting edge and a handle which is struck with a hammer, use to cut ~~or shape~~ ^{metal} metal.
- Angle between the working surface and lower cutting edge known as clearance angle.
- Angle betw upper cutting edge and normal to the working surface known as rake angle.
- The chisel is seen flat on the work if there is no clearance angle.



→ The clearance angle takes on actual part on the cutting on shearing action, but it is given on a tool to remove the loss of energy caused by the frictional resistance.



→ ~~using cold chisel with no clearance angle~~

Reamers

A reamer is a type of cutting tool used in metalworking to enlarge the size of existing hole. ~~by a small amount with~~

Dies

Taps & Dies

Taps & Dies are 2 tools used to create screw threads. ~~what is a tap~~

→ A tap is used to ~~cut~~ form thread on the ~~inner~~ ^{inner} surface of a hole.

→ Dies used to create external thread on cylindrical material such as rod

Lathe

The main function of a lathe is to remove metal from a piece of work to give it required shape and size.

→ This is accomplished by holding the work securely and rigidly on the machine and then turning it against the cutting tool which will remove metal from the work in the form of chips.

→ To cut the material properly the tool should be harder than the material of the work piece should be rigidly held on the machine and should be fed or progressed in a definite way relative to the work.

Description and function of Lathe parts

by Bed
by Headstock
by Tailstock
by Carriage
by feed mechanism

→ screw cutting mechanism

Bed

→ The lathe bed forms the base of the machine. The headstock and tailstock are located at either end of the bed and the carriage rests over the lathe bed and slides on it. The lathe bed being the main guiding member of the tool, for accurate milling work.